

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1029
East
> 1
1.340 mi.
7074 ft.

LOURDES RESIDENCE
210 CORBIN PL
BROOKLYN, NY

NY Spills S116155013
N/A

Relative:
Higher

Actual:
7 ft.

SPILLS:

Name: LOURDES RESIDENCE
Address: 210 CORBIN PL
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1308478 / 2016-05-27
Facility ID: 1308478
Facility Type: ER

DER Facility ID: 444314
Site ID: 489218
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2013-11-20
Investigator: SXMAHAT
Referred To: Not reported
Reported to Dept: 2013-11-20
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2013-11-20
Spill Record Last Update: 2016-05-27
Spiller Name: DANNY LOVARE
Spiller Company: LOURDES RESIDENCE
Spiller Address: 210 CORBIN PL
Spiller Company: 999
Contact Name: DANNY LOVARE
DEC Memo: "11/20/2013: Mahat DEC contacted Mr. Danny Lavare (Notifier @ 718.967.9424. He informed DEC that the tank was abandoned and it was never used. At the time of removal he discovered contaminated soil under the tank. DEC is waiting for the confirmation result from Mr. Lavare. DEC Require: 1. End point sample. 10/19/15: Mahat Laurdes Caso Derman [home owner] ***** Source DOB Website 718.646.6097 Made an attempt to contact the homeowner. 10/20/15: Mahat DEC Mahat left a voice message to the Home Owner requesting a call back with more information. 11/23/15: Mahat DEC Mahat received a call back from the home owner inquiring about the process of the spill closure. A list of contractor has been provided to the Home Owner. Tank has been removed from the site. One end point soil sample need to be collected for the confirmation. DEC is waiting for a end point result. 1/12/16: Mahat DEC Mahat left a voice message to home owner inquiring about the progress on the spill case. Cell : 646.251.1961 4/29/16: Mahat t/c: DEC Mahat talked to the homeowner inquiring about the end point sample collection. She mentioned that back fill and end point will happen some time this summer. A call back is scheduled for August for a follow up. 5/27/16: Mahat File Review: Based on the information provided to the Department to date, no further investigation is

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

warranted on the spill case. It will be closed on NYSDEC Spill Database. "

Remarks: "soil contamination found during tank removal, c/u in progress"

All Materials:

Site ID: 489218
Operable Unit ID: 1238807
Operable Unit: 01
Material ID: 2238757
Material Code: 0001A
Material Name: #2 fuel oil

Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported